

Submission of Concrete Mix Design Form B
Regional Head of Quality Assurance – MTO
(As of February 9, 2023)

As per the requirements of OPSS.PROV 1350, the following are the current names and contact information for the various Regional Heads of Quality Assurance:

CENTRAL REGION

Loan Le, P.Eng.

Head, Quality Assurance (A)
Construction Oversight Office, Central Region

Ministry of Transportation

159 Sir William Hearst Avenue

Toronto, ON M3M 0B7

Phone: 647-642-4859

Email: QACentralMixDesign@ontario.ca

EASTERN REGION

Gizelle Cotton, P.Eng.

Head, Quality Assurance
Construction Oversight Office, Eastern Region

Ministry of Transportation

1355 John Counter Blvd., Postal Bag 4000

Kingston, ON K7L 5A3

Phone: 613-217-7365

Email: gizelle.cotton@ontario.ca

WESTERN REGION

Jeffrey Giroux, P.Eng.

Head, Quality Assurance
Construction Oversight Office, West Region

Ministry of Transportation

659 Exeter Road, 2nd Floor

London, ON N6E 1L3

Phone: 519-319-5728

Email: QA.West@ontario.ca

NORTHWESTERN REGION

Gary Weiss, P.Eng.

Manager, Construction Oversight Northwest
Capital Program Delivery Branch

Ministry of Transportation

615 James Street South, Floor 2

Thunder Bay, Ontario P7E 6P6

Phone: 807-624-8883

Email: Gary.Weiss@ontario.ca

NORTHEASTERN REGION

Sonja Dambremont, P.Eng.

Head, Quality Assurance
Construction Oversight Office, Northeastern
Region

Ministry of Transportation

447 McKeown Avenue, Suite 301

North Bay, ON P1B 9S9

Phone: 705-497-5516

Email: sonja.dambremont@ontario.ca

Confirmation of the appropriate person for submission of Form B should be received from the Contractor or CA directly. When each Form B is submitted, a copy shall be sent to concretemixdesign@ontario.ca.

*RMCAO has inquired as to the **preferred method** of receiving the Form B information and the MTO has indicated that their preference for submission of this information is a hand-signed version of Form B scanned into PDF format and e-mailed directly to the appropriate Regional Head of Quality Assurance. If there is a problem with this format, alternative arrangements should be made in advance with the Regional Head of Quality Assurance.*